



Mount shown with wind sensors

DESCRIPTION

SDUM Support for Anemometer and Wind Vane

This assembly is designed to support the SLT three cup anemometer and DLT wind direction vane.

ASSEMBLY INSTRUCTIONS

1. Attach the anemometer and wind vane to the supporting 1/2" tube using the cotter pins.
2. Secure the sensors to the tube with a set screw in their base.
3. Note the orientation of the North arrow of the wind vane.
4. Slip the wind sensor assembly over the supporting mast and align the wind vane to True North.
5. Tighten the set screw attaching the wind sensor assembly to the 1" tube mast.

ORDERING INFO

PART NUMBER

SDUM U-Mount Assembly

